
Measurement Conversion Chart

product advice & information sheet

Measurement Conversion Chart

MM	IRON	INCHES	FRACTIONS
1	1.8	.039	1/32
2	3.8	.079	
3	5.6	.118	1/8
4	7.5	.157	5/32
5	8.9	.197	3/16
6	11.3	.236	1/4
7	13.3	.276	
8	15.1	.315	5/16
9	17.0	.354	
10	18.9	.394	
11	20.8	.433	7/16
12	22.7	.472	
13	24.6	.512	1/2
14	26.5	.551	9/16
15	28.3	.590	
16	30.2	.630	5/8
17	32.1	.669	
18	34.0	.709	
19	35.9	.748	3/4
20	37.8	.787	
21	39.7	.827	
22	41.6	.866	7/8
23	43.4	.905	
24	45.4	.945	
25	47.2	.984	1"